

You are reminded that Site Log Books are official documents and comments must be restricted to operational information and actions. Please write clearly and ensure that you sign in and out at all times. If you are concerned about any aspect of site performance or safety please contact your Line Manager as soon as you can.

Comments	Flow l/s	Weather Conditions	Site Security Checks	Samples					
				Visual Check	SS	NH ₃	P	Other Specify	FE Temp °C
new Start/Stop floats installed. Proven both operate properly when required.									
PARTS RETURNED , BACK IN SERVICE									
PITS ALL HIGH TO DESLUDGE, SHT DOWATERING HAD TO LEAVE DUE TO EMERGENCY.		SUNNY WARM	✓	SC	5	1.13	—		17.6
FIT NEW WATER HEATER, WATER NOW GETTING 'HOT'									
SCREEN NOT RUNNING, READING 0.05 ON LEVEL MONITOR, RAN IN HAND, NOW READING OK.	88	RAIN	✓	SC	5	0.86	1.2	0.53	17.5
^{INLET} JOB RAISED FOR LEVEL MONITOR, IN JOB BOOK SHT CRACKED TO DOWATER.	47	RAIN	✓	SC	5	0.76	1.0	0.26	17.2

Action Exp
CONTACT THE

