

Equipment & Plant removed/Installed	
tails	Due Date For Return

Comments	l/s	Conditions	Security Checks	Samples					
				Visual Check	SS	Nh	P	Other Specify	FE Temp °C
Pos 1-3 = 2.2m - weeds need pulling through the week - Siphon, humus bridges etc.		Sunny	OK	Rf	5	1.72	1.6	0.25 <i>1.2m</i>	18.4
Sample before leaving site, NH3= 0.69, SS= 5 Rf									
Job completed. Photos taken and sent via whatsapp, with info.	159	cloudy & wet	OK	Rf	5	2.04	1.7	0.33	17.3
* Cleared mass/weeds from Saf inlet.		cloudy & wet							
* De-watering / sludge tank over flowed - will clean-up once dry.	113		OK	Rf	5	0.89	1.4	0.29	17.6
* job raised for liquor (unable to reset) - will pump replaced, tested in manual and auto making us should.									
Unblocked new from de-water pump 2 and cleared weeds from humus diversion	110	O/cg & Dry	OK	Rf	5	0.31	1.6	0.27	18.9

This template is available at: AW\_hh\_us\_bsy/Publish/Electronic Document Control Library/Poswastes/Forms and Templates  
 Template: Revision 2, Dated August 2009