

61673904 WR530 EA SB CAT 3

WWICST, West Wickham Stw, Webbs Road, West Wickham, Cambridge, CB21 4RY

General 20/12/2022 20:45
20 days ago

Affected Area Updated to Watercourse

Event Completed 17/12/2022 10:22

General 17/12/2022 09:42
24 days ago

Sample is back within limits and site is now running BAU. NFA required.

Category Update 17/12/2022 09:41
24 days ago

3

This event has been initially categorised as a CAT 3 (Medium Risk)

Categorisation Completed on 17/12/2022 09:41

Job Completed 17/12/2022 09:40

General 17/12/2022 09:33
24 days ago

From site visit op/job:-

17.12.2022 09:23:29 UK (BC-BATCH)

*****OFSC note added by AN 2022-12-17 09:20:05 *****

*****OFSC note added on *****

Site come down to what has been all ok on site Ss sc 10 Nh3 1.17

informed OCM 17/12/2022 09:34
24 days ago

General 17/12/2022 09:33
24 days ago

Photos from samples taken from EO point



General 17/12/2022 09:28
24 days ago

Called for update - 0.70 NH3, on hanna kit is 1.17 NH3 at set sample point, temp 5.4 on FE and 5.2 on filters and still waiting on M+E to check the plate on biofilter. He is just going to the FE EO point and getting some photos of the ditch and will send them across

Job Accepted ([redacted]) 17/12/2022 09:23

Arrived On Site ([redacted]) 17/12/2022 09:23

General 17/12/2022 08:59
⌚ 24 days ago

onsite on routines job

Job Assigned ([redacted]) 17/12/2022 07:29

General 17/12/2022 07:28
⌚ 24 days ago

Assigned to [redacted] ETA 08:58

General 17/12/2022 07:05
⌚ 24 days ago

no op has been added

op added now

General 17/12/2022 07:06
⌚ 24 days ago

Job Resumed ([redacted]) 17/12/2022 04:45

Job Paused ([redacted]) 16/12/2022 20:06

General 16/12/2022 13:18
⌚ 25 days ago






V/M left with [redacted] for an update - requested she call me back until 14:00PM and past that to message on whatsapp.

General 16/12/2022 10:12
⌚ 25 days ago

Updated DM and FLM. Stopping tankers tankering from site. Compliance check for the weekend

General 16/12/2022 09:10
⌚ 25 days ago

Photos from [redacted]

Job Completed ([redacted]) 16/12/2022 09:03

General 16/12/2022 08:46
⌚ 25 days ago

JOB TYPE **WR Pollution** WATCHED ★ RISK **Medium**

Op 0010


CATEGORISATION
3 Initial

STATUS
Event Completed

INFORMED 09:37 → ARRIVED 17:27 → COMPLETED 10:22
15/12/2022 15/12/2022 17/12/2022

Show Full Timeline

Business Unit	Water Recycling
Job Type	Pollution
Informed By	Anglian Water
Point of Entry	52.1129274622 0.3488449302
Discharge Consent	Yes
Asset Code	WWICST
Asset Type	Non-Infra
Asset Category	Unknown
EA in Attendance	No
EA Informed	Yes
NIRS Reference	2118642
Formal Sample	Unknown
Tankering	T1
Storm Condition	No
Watercourse Access	PIA Practical
Photos Added	Unknown
Affected Area	Watercourse



Address **West Wickham Stw,
Webbs Road, West
Wickham, Cambridge,
CB21 4RY**

Manager Patch **OPSH WR530**

PEOPLE (11)
[redacted]

[View Details](#)

No flow leaving site. Filter ammonia 3.06. Temp 4.3c, unable to upload photos. Left voicemail with duty manager to update on site.

■ [redacted] 16/12/2022 08:37
General 25 days ago

Called [redacted] for update - no flow leaving site, has been tankered all night from the humus tanks. 3.6 NH3 at testing point and consent is 4. He is going to the WC and get photos and if there is anything to sample (and safe to do so) he will get an ammonia sample at EO

★ [redacted] stopped watching this event 16/12/2022 08:24

■ [redacted] 16/12/2022 08:09
General 25 days ago

ft is now on site- orrt informed

[redacted] - Arrived On Site ([redacted]) 16/12/2022 08:07

★ [redacted] started watching this event 16/12/2022 07:51

■ [redacted] 16/12/2022 07:21
General 25 days ago

oracle ETA for [redacted] - 08:14 enroute

[redacted] - Job Accepted ([redacted]) 16/12/2022 07:16

[redacted] - Job Assigned ([redacted]) 16/12/2022 07:02

■ [redacted] 16/12/2022 06:58
General 25 days ago

not yet assigned

■ [redacted] 16/12/2022 00:47
General 25 days ago

Passed to SOM to publish and leave open


■ [redacted] 16/12/2022 00:46
General 25 days ago

Tankers on site stopping discharge



■ [redacted] 16/12/2022 00:45
General 25 days ago


Downstream



■ [Redacted]
General

16/12/2022 00:45
🕒 25 days ago

Upstream



■ [Redacted]
General

16/12/2022 00:42
🕒 25 days ago

POD



■ [Redacted]
General

16/12/2022 00:41
🕒 25 days ago

Snow



■ [Redacted]
General

16/12/2022 00:41
🕒 25 days ago

Humus tank below weir



■ [REDACTED]
General

16/12/2022 00:03
🕒 25 days ago

Temp



■ [REDACTED]
General

15/12/2022 23:56
🕒 25 days ago

FE amm (10x dilution)



OP 0010 - Job Completed ([REDACTED])

15/12/2022 22:24

■ [REDACTED]
General

15/12/2022 21:29
🕒 25 days ago

Spoke to [REDACTED] who was on site with routines mid day on a different job no.

■ [REDACTED]
General

15/12/2022 21:04
🕒 25 days ago

This job has been risk assessed as high, please add the Risk Assessed High group tag to the PCC card, then amend the PCC priority to high (if not already)

■ [REDACTED]
ORRM informed

15/12/2022 21:05
🕒 25 days ago

■ [REDACTED]
General

15/12/2022 21:03
🕒 25 days ago

TTB states HI BALANCE TANK CAN RESULT IN FLOODING OF BIO FILTERS - NO COMPLIANCE ISSUES AT PRESENT
Only power required for return pump, hi wet well will be ok until next day.

General


15/12/2022 21:02
🕒 25 days ago

Discharge consent - Yes
TL609485

General

15/12/2022 21:01
🕒 25 days ago

View X shows inlet running normal and healthy.



General

15/12/2022 21:00
🕒 25 days ago

GNet shows a 6inch FS & 4inch RM flowing into Site. No SWS in area. Nearest WC approx. 8m from site



General

15/12/2022 20:55
🕒 25 days ago

Magic maps shows postcode in SPZ3 and Slightly in SPZ2. No SSSI. Although not in the direct area there is Over Lawn Woods (SSSI) approx. 800m from area.



General

15/12/2022 20:47
🕒 25 days ago

Access to Water for PIA - Yes
In daylight - currently focusing on resolving the issue on site

General

15/12/2022 20:47
🕒 25 days ago

Storm condition - No

General

15/12/2022 20:47
🕒 25 days ago

Tankering type - T1
Two tankers on site C224137

 
General 15/12/2022 20:46
🕒 25 days ago

Point of Impact is updated.


 
General 15/12/2022 20:46
🕒 25 days ago

Informed By updated to Anglian Water

★  started watching this event 15/12/2022 20:46

SU **System User**
General 15/12/2022 20:46
🕒 25 days ago

Work Order fetched manually from SAP

Arrived On Site () 15/12/2022 17:27

Job Accepted () 15/12/2022 15:32

Job Assigned () 15/12/2022 11:01

Created (System User) 15/12/2022 09:37



Weather

West Wickham Stw, Webbs Road, West Wickham, Cambridge, CB21 4RY
15/12/2022 09:37



-7°
07:00



-7°
08:00



-6°
09:00




-5°
10:00



-4°
11:00



Scheduling

Reported On 15/12/2022 09:37
Assigned to 



Job Description
BIOFILTER 1+2 ROTATION FAILED



Work Order No
61673904



SLA
NA